

DRMS Coal New Revision Application



COLORADO

**Division of Reclamation,
Mining and Safety**

Department of Natural Resources

Login

General Information

Revision Application Form Selection *

MR (Minor Revision Application)

Permit Number *

C1980007

Operation Name

West Elk Mine

The following pages will show the contact information we have on file for this permit. If any of it is inaccurate, you will have the opportunity to correct it after this form has been submitted.

1. Upon submission of this form you will be presented with a link to the contact information update form.
2. There is a question asking about the accuracy of this information. Indicating that it is inaccurate will send an e-mail to notify your administrator to make the appropriate changes.

Contact Information

Permittee Contact Information

Permittee Name

Mountain Coal Company, LLC

Permittee Contact

Weston Norris

Permittee Address 1

5174 Highway 133

Permittee Address 2**Permittee City**

Somerset

Permittee State

CO

Permittee Zip Code

814340000

Permittee Contact Email Address

wnorris@archrsc.com

Permittee Contact Phone Number

Permitting Contact Info

Permitting Name

Mountain Coal Company, LLC

Permitting Contact

Kathleen Welt

Permitting Address 1

5174 Highway 133

Permitting Address 2**Permitting City**

Somerset

Permitting State

CO

Permitting Zip Code

814340000

Permitting Contact Email Address

kwelt@archrsc.com

Permitting Contact Phone Number

9709292238

Inspection Contact Info

Inspection Name

Mountain Coal Company, LLC

Inspection Contact

Kathleen Welt

Inspection Address 1

5174 Highway 133

Inspection Address 2

Inspection City

Somerset

Inspection State

CO

Inspection Zip Code

814340000

Inspection Contact Email Address

KWelt@archrsc.com

Inspection Contact Phone Number

9709292238

Is the contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *

☒ Yes ☐ No

Once this form is submitted you will see a link to update contact information, which you may do if you're an admin.

Surface Area Changes

Revision

Revision Title * (?)

MR-452: Repair of South Prong Subsidence Basin

Short description

Narrative Description of Revision * (?)

Repair of subsidence basin by backfilling with nearby native soils, injecting the backfill with cementitious grout and sealing the area with a bentonite cap.

Detailed description used for notifications

Bond Amount Change? *

☐ Yes ☒ No

Additional Surface Disturbance? *

☒ Yes ☐ No

Proposed Acreage Revisions

Permit Area

Current Value

19855.00

Proposed Change Value * (?)

0.00

Calculated Revised Total

19855.00

This value must equal the total of all Surface and Mineral Acreage changes

Affected Area

Current Value

15953.00

Proposed Change Value * (?)

0.00

Calculated Revised Total

15953.00

Disturbed Area

Current Value

577.00

Proposed Change Value * (?)

0.60

Calculated Revised Total

577.60

Attachments & Maps

Do you have attachments? *

☒ Yes ☐ No

Attachments

Standard Uploads

Document, NOT Confidential

MR-452 Repair of S Prong Subsidence Basin.pdf	413.16KB
2.05-170.pdf	87.77KB

Map, NOT Confidential

MR-452-M34-36X24.pdf	922.22KB
----------------------	----------

Confidential Uploads

CONFIDENTIAL Document

CONFIDENTIAL Map

Document / Map List

New or Revised Documents / Pages *

If none exist, enter NONE in the comment box below.

2.05-170

New or Revised Maps *

If none exist, enter NONE in the comment box below.

Map 34

Deleted Documents / Pages *

If none exist, enter NONE in the comment box below.

None

Deleted Maps *

If none exist, enter NONE in the comment box below.

None

Signature

Date

10/16/20

By checking this box you have thoroughly reviewed this Coal Revision form and are ready to submit this form to DRMS.

☒ I Agree