




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Flying Triangle Ranch Pit	MINE/PROSPECTING ID#: M-2008-018	MINERAL: Sand and gravel	COUNTY: Moffat
INSPECTION TYPE: Surety-Related Inspection	INSPECTOR(S): Clayton Wein	INSP. DATE: November 12, 2020	INSP. TIME: 09:00
OPERATOR: Flying Triangle Ranch, LLC	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Surety Related	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$21,368.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: November 12, 2020	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was an inspection of the Flying Triangle Ranch Pit, M-2008-018, conducted on November 12, 2020. The inspection was completed by Clayton Wein of the Division. The inspection was conducted in response to a Succession of Operators Application (SO-2) that was submitted to the Division. No company representative was present for the inspection due to the inspection being conducted via Google Earth. The weather was clear and the ground conditions appeared to be dry.

Financial Warranty:

The Division calculated the amount required to reclaim the site in its current condition to be \$20,283.00. The Division will not request an increase in the surety at this time.

Hydrologic Balance:

The site was dry during the inspection. No off-site impacts were observed. There were no locations with ponded water that would impact mining or reclamation activities.

Gen. Compliance With Mine Plan:

The permitted site is a 112c and is 61 acres in size of which 3.3 acres are requiring reclamation. The mine site is located approximately 41 miles northwest of Craig, CO. The site is located south of the state line, and the nearest town is Baggs, WY. There has been no recent mining activity. The site is composed of three main areas; the western pit (Photo 1), the middle area with stockpiles (Photo 2), and the eastern area which is undisturbed (Photo 3). The Division has observed no changes in the mine site since the July 18, 2019 inspection.

Photographs



Photo 1: The western portion of the permitted area containing the mine pit.



Photo 2: The middle portion of the permit area containing the stockpiles.



Photo 3: The eastern portion of the permitted area is undisturbed.

Inspection Contact Address

None
Flying Triangle Ranch , LLC
12602 US HWY 26
RIVERTON, WY 82501

Enclosure

CC: Jason Musick, Division of Reclamation, Mining and Safety.