

## **PERMIT INFORMATION**

Permit Number: C-1981-037 Mine Name: GEC Strip Mine Operator: GEC Minerals, Inc. Operator Address: Dr W Corley 2605 Constellation Drive Colorado Springs, CO 80906	County: Fremont Operation Type: Surface Permit Status: Revoked Ownership: Private  Operator Representative Present:
Operator Representative Signature: (I	Field Issuance Only)

## **INSPECTION INFORMATION**

Inspection Start Date: December 27, 2020 Inspection Start Time: 13:00 Inspection End Date: December 27, 2020 Inspection End Time: 13:10			Inspection Type: Coal Comp. Inspection Reason: Normal Id Weather: Clear	•
Joint Inspection Agency:		<b>Joint Inspection Contacts:</b>		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspecto	r's Sig	nature:	Signature Date:
Zach Trujillo	30	1-	56	12/29/20

## **Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection N - Roads

N - Availability of Records N - Reclamation Success

N - Backfill & Grading
N - Revegetation

N - Excess Spoil and Dev. Waste

N - Subsidence

N - Explosives
 N - Slides and Other Damage
 N - Fish & Wildlife
 N - Support Facilities On-site
 N - Signs and Markers

N - Gen. Compliance With Mine Plan

N - Support Facilities Not On-site

N - Other N - Special Categories Of Mining

N - Processing Waste N - Topsoil

## **COMMENTS**

This was a complete inspection of the GEC Mine conducted by Zach Trujillo of Colorado Division of Reclamation, Mining and Safety (DRMS) on December 27, 2020. The GEC Mine was a surface mine which the Division has revoked the bond and terminated the permit. Therefore, no mine operator remains. All bond monies available to the Division were utilized by the Divisin for reclamation activitries and no reclamation bond money remains to conduct maintenance activities. The weather was clear and ground conditions were dry. Temperatures during the inspection were around seventy degrees fahrenheit.

On November 13, 2018, a meeting was held between the Division and The Corley Company in regards to the Division's intentions of releasing jursidiction to the GEC Mine Site. During this meeting, Dr. Corely, president of The Corley Company, informed the Division that it was best that the Division no longer access the site on the lands owned by The Corely Company. Based upon that meeting, this inspection was done from a limited public access point at the gated county road. The lock code that the Division once had to this gate no longer works.

The inspection for the GEC Mine was done at the locked gate along the county road to the site. A portion of Chen's Hill was visible from this location. From that location, no rills or gullies could be observed due to the line of sight as well as snow cover. As docuemtend in previous reports, the slope has multiple gullies. The embankment of the Pond A was inspected from the county road. The pond has been prevriously reported as filled with sediment.





Number of <u>Partial</u> Inspection this Fiscal Year: 0 Number of <u>Complete</u> Inspections this Fiscal Year: 1