



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

April 27, 2021

Louis Head
New Elk Coal Company, LLC
12250 Highway 12
Weston, Co 81091

RE: Lorencito Canyon Mine, Permit C-1996-084
1st Quarter 2021 – Lorencito Canyon Mine Quarterly Fill Inspection Report

Dear Mr. Head:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in general compliance with the following CDRMS regulations:

- 4.09.1(11)(a) *Inspected at least quarterly by a reregistered engineer or other qualified professional specialist in construction of earth and rockfill embankments under the direction of a qualified engineer throughout the construction.*
The certified report covers the first quarter monitoring period from January to March of 2021, and the inspections were conducted by yourself, a certified engineer on March 17, 2021. No discrepancy were noted.
- 4.09.1(11)(b) *Provide to the Division a certified report within 2 weeks after each inspection that the fill has been constructed as specified in the design approved by the Division. The report shall include a description of any appearances of instability, structural weakness, and other hazardous conditions.*
The inspection was conducted on March 17, 2021. The Division received the report on March 29, 2021. No instability, structural weakness, or other hazardous conditions were noted during this inspection of the fill.

If you have any questions feel free to contact me at (303) 866-3567, extension 8126.

Sincerely,

Daniel Cunningham
Environmental Protection Specialist

