

Notes:

Please refer to the 2021 Annual Report Map for the location of the areas discussed below.

7. The following list outlined the various areas of disturbance at the mine

Description	Acres
Landowner Borrow area	0.47 (brown)
Grading, shaping and resoiling complete	8.75 ( yellow)
Slope grading complete	2.60 (Cross hatched)

10. Approximately 2.00 acres was sloped last fall and the entire area except the Landowner Borrow Area was resoiled with an average of 5 inches of growth medium over the winter.

12. Seeding was due this spring but the wet conditions at the site prevented seeding. We expect that to happen as soon as the area dries out and is accessible to prepare the seed bed and plant the grass.

18. The bond was evaluated in January 2017 and covers 20 acres of reclamation. The \$34,450.00 is adequate to cover the reaming seeding cost.