



June 24, 2021

Dorn Ready Mix Corp.  
19671 Rd R 7  
Fort Morgan, CO 80701

**RE: Barlow Pit, M-1974-092**  
**Receipt of Corrective Action Technical Revision #2**

Dear Mr. Dowling,

The Division received Technical Revision #2 (TR2) for the Compliance Problems cited in the Division's inspection report that was conducted on March 19, 2021. The status of the corrective actions in regard to the cited problems are as follows:

**Problem:** The affected area/permit boundary markers are missing. This is a problem for failure to maintain boundary markers around the affected area as required by Section 3.1.12(2) of the rule.

**Corrective action:** The operator shall conduct a survey and replace the boundary markers in the correct location(s). The operator shall provide proof to the Division that this has been done by the corrective action date. The operator shall submit a technical revision, with the required \$216 revision fee, to update the permit boundary legal description (Rule 6.4.1), the mining plan map (Rule 6.4.3) and the reclamation map (Rule 6.4.6) showing the permit boundary on each map. The Technical Revision needs to be submitted within 60 days of this report.

The Division has approved TR-2 and the cited problem is considered resolved.

If you have any questions, please contact me at (303) 866-3567 ext. 8142 or [brock.bowles@state.co.us](mailto:brock.bowles@state.co.us).

Sincerely,

Brock Bowles  
Environmental Protection Specialist

cc: Michael Cunningham, DRMS

