

Notes:

Please refer to the 2021 Annual Report Map for the location of the areas discussed below.

The following list outlined the various areas of disturbance at the mine

Description	Acres
Topsoil Piles 11,600 cyd	1.5 (yellow)
Active mining area	3.37 (tan)
Mine floor/Plant site	24.15 (brown)
Spring	NA (blue)
Total disturbance	27.52 (/// hatched)

The mine floor is industrial area so does not need resoiling.

9. Approximately 3.37 acres was partially mined this year. Mining will continue on this area. Material was also removed from stockpiles.

19. The bond was evaluated in 9/22/2018 by the Division. The \$62,700 is adequate to cover the reclamation cost.

21. No groundwater monitoring information is provided . The permit called for only 8 quarters of data and the last data submitted covered 44 quarters ending in May 2018. There is no exposed groundwater on the mine. The natural spring has been isolated on the north east side and the water diverted tot he natural drainage on the north.