

Notes:

9. Mining continued in the dry creek channel that was disturbed in years past (brown).

10. We continued to place material in the Backfill area along the south and east sides of the old mined area (yellow). No other reclamation is required at this time. Approval of importing inert materials to backfill the old mine area was issued on 10 May 2019.

15. As noted in the Mining and Reclamation Plans there is no topsoil to salvage from the mining area.

19. The bond was evaluated by the Division in May 2019 and found to be adequate to complete reclamation.

22. Please refer to the 2021 Annual Report Map for location of the areas of disturbance in the mine.