



September 27, 2021

Jeff Harms  
McAtee Construction Company  
P.O. Box 1908  
Sterling, CO 80751

**RE: Bolish Pit #2 (M-2007-013)**  
**Receipt of Corrective Action Documentation**

Dear Mr. Harms,

The Division received your above referenced response to the Compliance Problems cited in the Division's inspection report that was conducted on August 25, 2021. The status of the corrective actions in regard to the cited problems are as follows:

**Problem:** The mine identification sign was not posted at the entrance of the mine site. This is a problem for failure to post a mine identification sign as required by Section 3.1.12(1) of the rule.

**Corrective action:** The Operator shall submit a photo documentation that a proper sign has been posted by the corrective action date.

The Division received photo documentation of the entrance sign post at the site and the problem is considered resolved.

If you have any questions, please contact me at (720) 774-0040 or [brock.bowles@state.co.us](mailto:brock.bowles@state.co.us).

Sincerely,

Brock Bowles  
Environmental Protection Specialist

cc: Michael Cunningham, DRMS

