



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

November 2, 2021

Leroy Garcia
R E Monks Construction Co.
P.O. Box 25579
Colorado Springs, CO 80936

RE: Mitchell Mine No 1, Permit No. M-1986-025, Follow-up on Unresolved Problem

Dear Mr. Garcia,

The above-mentioned site has a problem which according to Division of Reclamation, Mining and Safety records has not yet been resolved. According to our records, the following problem was to be resolved on or before October 26, 2021. Listed below is the description and corrective action for the problem. **Please resolve the corrective action or provide evidence of such resolution on or before January 2, 2022.** Failure to complete this corrective action may result in an enforcement hearing before the Mined Land Reclamation Board and possible civil penalties.

INSPECTION TOPIC: Sediment Control

PROBLEM/POSSIBLE VIOLATION: Problem: A large erosion gully was observed on-site. This is a problem at this time for failure to protect the affected land from erosion pursuant to C.R.S. 34-32.5-116 (4) (j).

CORRECTIVE ACTIONS: The operator shall provide photo documentation to the Division verifying the erosion gully has been repaired, and that the site has have been reconstructed and stabilized to prevent erosion damage by the corrective action date.

CORRECTIVE ACTION DUE DATE: 10/26/21

If you have any questions or need further information, please contact me on my cell phone at (303)328-5229.

Sincerely,

Timothy A. Cazier, P.E.
Environmental Protection Specialist

ec: DRMS file

