

STATE OF
COLORADO

Cazier - DNR, Tim <tim.cazier@state.co.us>

Fwd: Technical Revision adjusted

1 message

Hill Top Gravel LLC <hilltopgravel@gmail.com>
To: "Cazier -, Tim" <tim.cazier@state.co.us>

Tue, Dec 14, 2021 at 4:05 PM

Please see the attachments below. The kmz map and the recommended adjustments for technical revision.

Thank you ,

Blake

----- Forwarded message -----

From: **Blake Tope** <topecattle@gmail.com>

Date: Tue, Dec 14, 2021 at 5:04 PM

Subject: Technical Revision adjusted

To: <hilltopgravel@gmail.com>

2 attachments**Simla Hwy Pit Map.kmz**

1K

**Technical revision quote.docx**

15K



Simla Hwy

125

Simla Hwy
Google Earth



1. In the new map, located in the North West corner of the permit (colored in blue) is the new requested area to mine. Located south of that (colored in orange) is where the top soil will be stock piled.
2. Sediment pond will remain a sediment pond with no further adjustments to the map.
3. The new mining area is approximately 1.5 acres. Below is the estimated costs for the bond calculation
 - Top soil (1.5 acres) 1,210 cubic yards - all ready on sight.
 - Seed (1.5 acres) 60 lbs per acre – @ \$15.00 per lb = \$1,800
 - Equipment & labor (1.5 acres) \$100 per hour – approx. 10 hours = \$1,000Total = \$2,800
4. Top soil will be located in the orange segment of the map.