## **PERMIT INFORMATION**

Permit Number: C-1982-056 Mine Name: Foidel Creek Mine Operator: Twentymile Coal, LLC Operator Address: Ms Miranda Kawcak 29515 Routt County Road No. 27 Oak Creek, CO 80467	County: Routt Operation Type: Underground Permit Status: Active Ownership: Private  Operator Representative Present: Kevin Copeland				
Operator Representative Signature: (Field Issuance Only)					

# **INSPECTION INFORMATION**

Inspection Start Date: December Inspection Start Time: 10:00 Inspection End Date: Inspection End Time:	13, 2021		Inspection Type: Coal Partia Inspection Reason: Normal I Weather: Clear	*	
Joint Inspection Agency: Jo		Joint	Joint Inspection Contacts:		
None					
Post Inspection Agency: Post		Post	Post Inspection Contacts:		
None					
Inspector(s):	Inspector	pector's Signature: Signature Date:			
Tabetha Lynch	Tatha	Fig	noh	12/20/21	

#### **Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

N - Availability of Records

N - Backfill & Grading

Y - Excess Spoil and Dev. Waste

Y - Explosives

Y - Fish & Wildlife

Y - Hydrologic Balance

**R** - Gen. Compliance With Mine Plan

N - Other

Y - Processing Waste

Y - Roads

N - Reclamation Success

**R** - Revegetation

N - Subsidence

N - Slides and Other Damage

N - Support Facilities On-site

N - Signs and Markers

N - Support Facilities Not On-site

N - Special Categories Of Mining

N - Topsoil

### **COMMENTS**

This was a partial inspection of the Foidel Creek Mine; DRMS Permit No. C-1982-056, operated by Twentymile Coal, LLC. (TC). This inspection was conducted by Tabetha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division). Stream buffer signs were checked and in place during the inspection. Historical school appeared untouched. Please not Divisions items at the 7E pad listed below.

#### GENERAL MINE PLAN COMPLIANCE:

At the 7E, cement drop pad, permitted by the Division under TR97, multiple structures were noted by the Division at the time of inspection. Per the operator these are temporary structures owned by the contractor for the required cement work required. However these structures are not currently accounted for within the Divisions reclamation cost estimate. Please provide the Division with an MR including these temporary structures in the reclamation cost estimate (RCE) or provide the Division a rational on why these structures have not been included in the RCE. Photos are below.

T





REVEGETATION – Rule 4.15 Vegetative Cover; Timing:

Pipeline corridors have been/are being reseeded for the new pads.

DOCUMENTS RECEIVED

OTHER (SPECIFY)