

Zuber - DNR, Rob <rob.zuber@state.co.us>

Inspection report

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us> To: "Moline, Ben" <ben.moline@molsoncoors.com> Mon, Feb 28, 2022 at 8:01 AM

Good morning, Ben.

Please see the attached report. Regarding the missing records, is there another pace in the site office where I should look for these? I expect that they should mostly be in the big 3-ring binder (with exceptions like ARR and AHR). As far as I can tell, you are not storing new documents in the file cabinets. Please let me know if I am missing something.

Also, the binder is full, and I suggest that you start a new binder with the reports that get updated on a regular basis. This could include the monthly DRMS reports and the quarterly reports that you create (ponds, etc.).

Thanks, Rob

Rob Zuber, P.E. Environmental Protection Specialist Active Mines Regulatory Program



COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

I am working remotely and can be reached by cell at 720.601.2276.

Physical Address: 1313 Sherman Street, Room 215 Denver, CO 80203 Mailing Address: Division of Reclamation, Mining and Safety, Room 215 1001 East 62nd Avenue Denver, CO 80216 rob.zuber@state.co.us | http://drms.colorado.gov

INSP-REPORTC_C1981028_RDZ_02282022051459.pdf 1088K



PERMIT INFORMATION

Permit Number: C-1981-028 Mine Name: Keenesburg Strip Mine Operator: Coors Energy Company Operator Address: Mr. Ben Moline PO Box 4030 Golden, CO 80402 County: Weld Operation Type: Surface Permit Status: Permanent Cessation Ownership: Private

Operator Representative Present:

None

Operator Representative Signature: (Field Issuance Only)

INSPECTION INFORMATION

Inspection Start Date: February 25, 2022 Inspection Start Time: 13:40 Inspection End Date: February 25, 2022 Inspection End Time: 15:15			Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post	Inspection Contacts:	
None				
Inspector(s):	Inspecto	r's Sig	nature:	Signature Date:
Robert Zuber, P.E.	Phot	D.	21-	
				2/28/2022

Inspection Topic Summary

NOTE:	Y =Inspected	N=Not Inspected	R =Comments Noted	V=Violation Issued	NA=Not Applicable
Y - Ai	r Resource F	Protection		NA - Roads	

- **R** Availability of Records
- NA Backfill & Grading
- NA Excess Spoil and Dev. Waste
- NA Explosives
- **R** Fish & Wildlife
- **R** Hydrologic Balance
- **R** Gen. Compliance With Mine Plan
- N Other
- NA Processing Waste

NA - Roads
R - Reclamation Success
R - Revegetation
NA - Subsidence
Y - Slides and Other Damage
Y - Support Facilities On-site
R - Signs and Markers
NA - Support Facilities Not On-site
NA - Special Categories Of Mining
NA - Topsoil

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on February 25, 2022. No Coors Energy Company (CEC) representative was present at the inspection. The site is in Permanent Cessation. Reclamation activities were completed in the fall of 2020, however, due to poor success in some areas, Coors Energy is preparing to reclaim these areas a second time. In several areas, stockpiles of soil amendments (Biosol fertilizer, phosphate) were seen.

The weather was cold, and the ground was partially covered with snow.

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

Recent reports (e.g., insurance document, Division inspection reports, and pond inspection reports) were not found in the binder where they should be filed. In future months, the records need to be current. Please see the list of records below.

FISH and WILDLIFE – Rule 4.18:

Across the site, birds and animal tracks (mouse, rabbit, and coyote) were seen.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Sediment Pond 2 and the Dugout Pond contained little to no water (thick vegetation obscures the bottoms). Neither pond was discharging during the inspection. There were no signs that they had discharged recently. No problems were observed with the two ponds.

GENERAL MINE PLAN COMPLIANCE:

The eastern portion of the northern boundary of the site was observed, and no signs of pollutant loading from the mine site, or any other problems, were seen.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

Large bare spots were seen at the east side of the reclaimed B Pit and at the southern portion of the reclaimed Long Term Spoil Area.

REVEGETATION - Rule 4.15

Vegetative Cover; Timing:

Decent vegetation was seen at the north end of Area 25. Sunflowers and undesirable species (cheat grass, kochia, and Russian thistle) are the predominant species in most of the newly reclaimed areas. These include the reclaimed road adjacent to Sediment Pond 2, Area 42, and the center of the reclaimed Long Term Spoil Area. Grasses were sparse at many newly reclaimed areas.

SIGNS AND MARKERS – Rule 4.02:

The entrance sign contained all necessary information.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Northern portion of Area 25



Stockpile of soil amendments at Area 42, with northern boundary in the background



Stockpile of soil amendments in Long Term Spoil Area (reclaimed), Looking southeast from the center of the area



Bare spot in B Pit Area (reclaimed), looking northwest from east side



Bare spot near south end of the Long Term Spoil Area (reclaimed)



Motor scraper and other reclamation equipment at the facility area

	AVAILABILITY	OF RECORDS	
PERMIT RECORDS		HYDROLOGIC RECORDS	
DRMS Permit	Exp. 11/3/2021	NPDES Permit	NA
	(new one pending		
	with RN-08)		
Permit Application w/Revisions	yes	NPDES Records	NA
Findings Document	RN-07 (Aug 2017)	Stormwater Management Plan	NA
Insurance Certificate	Exp. 11/1/2021	SPCC Plan	Updated 2012
Bond Document	\$1,197,459	MSHA Pond Inspections	NA
	(March 2016)		
Phased Bond Release	SL-09		NA
Documents/Findings	(SL-10 missing)	State Engineer's Pond Inspection	
Air Emission Permits	123008803	Quarterly Pond Inspections	Missing 2021
			reports
County Special Use Permits	Weld #1160, #386	Annual Hydrology Reports	2020
UG Mining Landowner Notification	NA	 Ground Water Monitoring 	yes
Subsidence Monitoring Reports	NA	 Surface Water Monitoring 	NA
Subsidence Monitoring Data	NA	 Spring & Seep Monitoring 	NA
Rill & Gully Survey	NA	 Mine Water Discharge Monitoring 	NA
Vegetation Monitoring Data	2020 ARR	 Mine Inflow Study 	NA
Specific Variance Approvals	NA	 Water Consumption Records 	NA
Annual Reclamation Reports	2020	Well Permits	*2
Midterm Review Documents	MT-07 (May 2019)		
DRMS/OSM Inspection	Through		
Reports/Enforcement Actions (3 Yrs)	February 2020	BLASTING RECORDS	
Transfers/Succession of Operator	NA	Blasting Publication	NA
Temporary Cessation Notification	NA	Blasting Records (3 years)	NA
Reclamation Cost Estimate	SL-09 *1	ATFE Explosives Permit	NA *3
CERTIFICATIONS		Blasting Variances	NA
Pond Certifications	Yes	Pre-Blast Surveys	NA
Annual Certifications for Large	NA	-	
Impoundments			
Fill Certifications for Excess Spoil or	NA	ADDITIONAL RECORDS (specify)	
Underground Development Waste			
 Quarterly Inspections 	NA	Pest and Weed report	Not found
 Compaction Testing 	NA		
 Final Certification 	NA		
Coal Processing Waste Banks	NA		
Haul Road Certifications	NA		
Access Road Certifications	NA		
COMMENTS:			
*1 Should be RCE from May 2020 for \$	1,078,021		

*2 Domestic use well and fire protection well (048289f, 24650f) *3 No explosives used since 1995.