

Annual Report of

Conditions: 11-2000-03

LEGEND


- PERMIT BOUNDARY
- EXIST. CONTOUR
- UNDY. DISTURBED AREA
- DIRECTION OF MINING
- PROPERTY LINE
- MONUMENTED BNDRY 5/8" REDAR



100' in feet



ENTRUSTED TO THE STATE



Actual Disturbed area

Topsoil Bank w/ Temporary Seeding

Stabilized Shale Pile

Active operations ceased in July 2000

Mining Notes

1. Mining shall begin at the site of the exi