



March 28, 2022

Chris Eisenhard
4406 Alaska LLC
5210 Getaway Drive
Berthoud, CO 80513

RE: 4406 Alaska, LLC Pit #1, M-2010-036
Receipt of Corrective Actions

Dear Mr. Eisenhard,

The Division received photos for the Compliance Problems cited in the Division's inspection report that was conducted on January 12, 2022. The status of the corrective actions in regard to the cited problems are as follows:

Problem #1: Erosion gullies and ruts were observed on-site. This is a problem at this time for failure to protect the affected land from erosion pursuant to C.R.S. 34-32.5-116 (4)(j).

Corrective action #1: The operator shall provide photo documentation to the Division verifying erosion gullies and ruts have been repaired, and that the site has have been reconstructed and stabilized to prevent erosion damage by the corrective action date.

Problem #2: The mine identification sign was not posted at the entrance of the mine site. This is a problem for failure to post a mine identification sign as required by Section 3.1.12(1) of the rule.

Corrective Action #2: The operator shall, at the entrance of the mine site, post a sign which shall be clearly visible from the access road with the following: the name of the operator, a statement that a reclamation permit for the operation has been issued by the Colorado Mined Land Reclamation Board; and the permit number. The operator shall submit photo documentation that a proper sign has been posted by the corrective action date.

The Division has received photo documentation showing that a mine entrance sign has been installed and the erosion gullies have been repaired. Both of the cited problems listed above are considered resolved.

If you have any questions, please contact me at (303) 866-3567 ext. 8142 or brock.bowles@state.co.us.

Sincerely,





Brock Bowles
Environmental Protection Specialist

cc: Michael Cunningham, DRMS