




**PERMIT INFORMATION**

<b>Permit Number:</b> C-1982-056 <b>Mine Name:</b> Foidel Creek Mine <b>Operator:</b> Twentymile Coal, LLC <b>Operator Address:</b> Ms Miranda Kawcak 29515 Routt County Road No. 27 Oak Creek, CO 80467	<b>County:</b> Routt <b>Operation Type:</b> Underground <b>Permit Status:</b> Active <b>Ownership:</b> Private
	<b>Operator Representative Present:</b>  Miranda Kawcak
<b>Operator Representative Signature: (Field Issuance Only)</b>  	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> May 3, 2022 <b>Inspection Start Time:</b> 09:00 <b>Inspection End Date:</b> May 3, 2022 <b>Inspection End Time:</b> 13:00		<b>Inspection Type:</b> OSM Partial Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Clear	
<b>Joint Inspection Agency:</b>  None		<b>Joint Inspection Contacts:</b>  	
<b>Post Inspection Agency:</b>  None		<b>Post Inspection Contacts:</b>  	
<b>Inspector(s):</b>  Tabetha Lynch	<b>Inspector's Signature:</b>  		<b>Signature Date:</b>  5/5/2022

**Inspection Topic Summary**NOTE: **Y**=Inspected **N**=Not Inspected **R**=Comments Noted **V**=Violation Issued **NA**=Not Applicable**Y** - Air Resource Protection**N** - Availability of Records**N** - Backfill & Grading**Y** - Excess Spoil and Dev. Waste**N** - Explosives**Y** - Fish & Wildlife**Y** - Hydrologic Balance**R** - Gen. Compliance With Mine Plan**N** - Other**N** - Processing Waste**Y** - Roads**N** - Reclamation Success**N** - Revegetation**N** - Subsidence**N** - Slides and Other Damage**N** - Support Facilities On-site**Y** - Signs and Markers**N** - Support Facilities Not On-site**N** - Special Categories Of Mining**R** - Topsoil**COMMENTS**

This was a partial inspection of the Foidel Creek Mine; DRMS Permit No. C-1982-056, operated by Twentymile Coal, LLC. (TC). This inspection was conducted by Tabetha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division). Miranda Kawcak of TC accompanied the inspection. Overall the weather was clear and warm during the inspection. The mine was mud and snow covered during the inspection. Please address bold items below.

**GENERAL MINE PLAN COMPLIANCE:**

**Please clean up coal that has been spilled near the stocker coal loadout, and ensure that the berm is adequate height to contain spills.**

Number of Partial Inspection this Fiscal Year: 6Number of Complete Inspections this Fiscal Year: 3

**Please clean up the coal that has been spilled at the train load out.**



Facilities area was muddy from snow melt and rain, please continue to work on clearing cultures and drainages as conditions allow.

7E pad cement drop project has been completed and temporary structures have been removed.



TOPSOIL – Rule 4.06

Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4:

**Please ensure the topsoil pile at the structure yard between ponds F and G is protected.** Cement

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 3

dividers are present to protect the topsoil pile, however some piping has fallen onto the topsoil pile. Please clean up piping and provided enough distance between stored items and the topsoil to prevent stored items from ending up on the pile.

**DOCUMENTS RECEIVED****OTHER (SPECIFY)****ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.

**AVAILABILITY OF RECORDS**

**Please submit the 2021 AHR**

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 3