



## COLORADO

Division of Reclamation,  
Mining and Safety

Department of Natural Resources  
1313 Sherman Street, Room 215  
Denver, Colorado 80203

October 30, 2017

Bryan Johnson  
PK Enterprises, Inc.  
11115 W. Hwy. 24, Unit 2A  
Divide, CO 80814

**Re: Receipt of Corrective Action Documentation, Mule Creek Pit, Permit No. M-2000-077**

Dear Mr. Johnson,

The Division received your response in regards to the Compliance Problem identified in the June 14, 2017 inspection report of the Mule Creek Pit. The status of the corrective action is listed below.

- **COMPLIANCE PROBLEM #1:** Silt fencing is not in place along western permit boundary in accordance with the approved permit. This is a problem pursuant to the approved permit, Rule 3.1.5(3), and Rule 3.1.6(3).
  - On October 25, 2017, the Operator's submitted photographic documentation showing new silt fence has been installed along the western permit boundary; **this problem has been resolved.**

If you need additional information or have any questions, please contact me at Division of Reclamation, Mining and Safety, 1313 Sherman Street, Room 215, Denver, CO 80203, by telephone at **303-866-3567 x8132**, or by email at [elliott.russell@state.co.us](mailto:elliott.russell@state.co.us).

Sincerely,

Elliott R. Russell  
Environmental Protection Specialist

Cc: Wally Erickson with DRMS

