

Notes:

Please refer to the 2022 Annual Report Map for the location of the areas discussed below.

8. The following list outlined the various areas of disturbance at the mine

<u>Description</u>	<u>Acres</u>
Growth medium Piles 28,500 cyd	1.6 (cross hatched)
Stripped area	5.2 (tan)
Plant site/part mined	30.6 (yellow)
Partially sloped	0.4 (/////)

Mining continued on areas previously disturbed and has reached the setback limits. The mined floor is being deepened. Slope reconstruction will begin this year along the south side using fines material from the processing plant.

10. No reclamation is required at this time. Sloping will continue next year.

13. Backfilling and sloping began on a 0.4 acre area along the south side.

19. The bond was evaluated in 9/9/2021 by the Division and increased to \$106,200.00 that is adequate to cover the reclamation costs for the disturbance at the mine.