



MEMORANDUM TO FILE

Date: July 12, 2022
To: DRMS Files
From: Rob Zuber, DRMS
RE: North Delta Pit (permit M-1979-002),
Corrective Action for markers

During the inspection of 5/17/2022, two problems were cited. One of them was insufficient boundary markers for the affected area, per Rule 3.1.12(2).

In an email of 7/12/2022, Derek Horn of the City of Delta wrote:

We have installed t-posts along much of the site perimeter. I have attached ... photos that accurately represent the site perimeter conditions ... t-posts have been driven along the site perimeter using information from our GIS Coordinator and survey pins on-site.

Mr. Horn sent six photos, and three are included in this memorandum.





Northeast corner, looking south



North perimeter, looking east



Southeast corner, looking north