

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: July 20, 2020

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

IT WAS NOTED DURING A STORMWATER INSPECTION ON 7/16/20 BY MARK MARTIN THAT THE EROSION CONTROL LOG BY THE OUTLET PIPE UNDER THE ROAD HAS SILT BUILD UP. WE WILL GO DOWN AND CLEAN THE AREA AND REPLACE THE LOG. IT IS STILL FUNCTIONING JUST TIME TO CHANGE IT.

Inspected by: STAN O.



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: JULY 20, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments: WARM DRY WEEK. EVERYTHING LOOKS GOOD.

Inspected by: STAN OPPERMAN

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: July 26, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

REMAINS HOT AND DRY.

Inspected by:

STAN O.



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: July 27, 2020

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

SEVERAL RAIN SHOWERS OVER THE WEEKEND. SHOULD HELP THE SEED. NO EROSION. SOME WATER IN THE DETENTION POND. EROSION CONTROL LOG @ PIPE UNDER WATER BOARD ROAD SHOULD BE REPLACED TOMORROW.

Inspected by: STAN O.

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: AUGUST 3, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

A FEW HEAVY SHOWERS RECENTLY. WATER IN
DETENTION AREA.

Inspected by: STAN OPPERMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: August 10, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

Hot And Dry

Inspected by:

STAN OPPEDMAN

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: AUGUST 16, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

NO CHANGES

Inspected by:

STAN OPPERMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection:

AUG. 23, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

HEAVY RAIN LAST THURSDAY (8/19/21). NO ISSUES
GOOD FOR THE GRASS AFTER LONG HOT PERIOD.

Inspected by:

STAN OPPERMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: Aug. 30, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

NO CHANGES. HOT AND DRY.

Inspected by: STAN OPPERMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: SEPT. 7, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments: HOT AND DRY.

Inspected by: STAN. O.



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: SEPT. 13, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

CONTINUED HOT AND DRY

Inspected by:

STAN O.



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: SEPT. 22, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

IT REMAINS WARM AND DRY.

Inspected by:

STAN OPPERMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: SEPT. 28, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

WARM AND DRY.

Inspected by: STAN OPPELMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: OCT. 4, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

WARM + DRY. SURVEY WAS DONE 10/1/21.
GROUND ENG. ON SITE 10/4/21 FOR SITE INSPECTION

Inspected by: STAN OPPERMAN

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection:

10/11/21

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

GETTING COOLER, SOME RAIN SHOWERS.
WAITING ON SURVEY INFO AND GROUND ENG. REPORT.

Inspected by:

STAN OPPERMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection:

OCT. 19/2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

NO CHANGES. SMALL AREA TO BE FILLED
(1' DEEP X 4' LONG) NOTED FROM GROUND ENG.
INSPECTION.

Inspected by:

STAN OPPERMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: OCT. 29, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments: STILL WARM + DRY. NO ISSUES.

Inspected by: STAN OPPERMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: 11/15/21

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

STILL DRY. GRASS IS DORMANT.

Inspected by:

STAN OPPERMAN



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: DEC. 3, 2021

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

A FEW WADDLERS NEED REPLACING. THEY WILL
BE TAKEN CARE OF TODAY OR MONDAY. WE WILL
PLACE SOME ROCK @ PIPE INLETS.
STILL WARM AND DRY.

Inspected by: STAN O.

