

# MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Wattenberg West Sand and Gravel Mine		M-2005-066	Sand and gravel	Weld
INSPECTION TYPE:		INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Surety-Related Inspection		Eric Scott	August 3, 2022	09:30
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Asphalt Paving Company		Mark Martin	112c - Construction Regular Operation	
DEACON FOR INCRECTION.		DOND CALCIU ATION TYPE.	DOND AMOUNT.	
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:	
Surety Related		Complete Bond	No Bond Held	
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA		None	None	
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:	
Clear	E	in Lut	August 4, 2022	

### **GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>NA</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING NA	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING NA	(SF) PROCESSING FACILITIES NA	(TS) TOPSOIL <u>NA</u>
(MP) GENL MINE PLAN COMPLIANCE- NA	(FW) FISH & WILDLIFE <u>NA</u>	(RV) REVEGETATION <u>NA</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN NA	(RS) RECL PLAN/COMP <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION NA	(ST) STIPULATIONS <u>NA</u>
(AT) ACID OR TOXIC MATERIALS NA	(OD) OFF-SITE DAMAGE <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: M-2005-066 INSPECTOR'S INITIALS: ECS INSPECTION DATE: August 3, 2022

#### **OBSERVATIONS**

The Wattenberg West Sand and Gravel Mine site was inspected by Eric Scott with the Division of Reclamation Mining and Safety (DRMS). On July 13, 2022 DRMS received a request for Succession of Operator for this permit from Asphalt Paving Company to Oldcastle SW Group, Inc. This site inspection was conducted to verify site conditions and the adequacy of the provided bond prior to approval of the permit transfer.

The site is permitted for 135 acres of sand and gravel mining with a post-mining land use of developed water storage, and is located on the south side of Hwy 6 approximately 1.5 miles north of Brighton CO. The site identification sign was located on the access gate on the west side of Caroline Ave as required (photo 1).

As indicated in the annual reports, no mining activity has commenced at the site to-date. The current activity on site is primarily agricultural (cornfield) and gas/oil production, Therefore the current bond of \$753,300 is sufficient until the operator is ready to commence mining activity (photos 2 and 3).

Most of the permit boundary is defined by existing fencing, however, prior to mining commencing the operator will need to fully define the permit boundary in the areas without fence or markers at this time. Areas noted that will need additional markers include along the SW corner and side, and in the east center area of the permit.

Prior to mining at the site, the operator will also need to submit a TR to the Division for approval to modify the minimum structure setbacks within the permit to comply with the minimum distances provided in the geotechnical stability evaluation submitted with SO2.

No other issues were noted during this inspection.

#### **Inspection Contact Address**

Mark Martin Asphalt Paving Company 14802 W 44th Ave Golden, CO 89403

## **PHOTOGRAPHS**



Photo 1-Site identification sign at east entrance to permit area.



Photo 3 – Looking NW into permit area from SE corner of permit near Weld County Road 4.5. Area is full of prairie dogs at this time.



Photo 2 – Looking east across permit area from Weld County Road 23 on west side of permit area.