



August 10, 2022

Tim Cazier
CO DRMS
1313 Sherman Street, Room 215
Denver, CO 80203

RE: Dawson Gold Project P-2020-002
Response to Surety Release Request Review dated August 8, 2022.

Dear Mr. Cazier,

Zephyr provides the following information in response to the Division's review.

(c) The location of disturbances included a drill pad, a water pump site, a waterline to the drill location and a helicopter landing site. This was a minimal disturbance site with all equipment and drilling personnel transported by helicopter. As such there was no site grading or top soil removal from any of the sites. Upon completion of drilling activity all equipment and waste materials were removed by helicopter and the areas were seeded with a high-altitude seed mix recommended by Arkansas Valley Seed. Straw was then applied as a stabilizer. The waterline location was over very rocky ground and as such there was no ground surface disturbance by the waterline. The helicopter landing pad was a historic railroad bed that did not display vegetation disturbance and was the same before and after drilling operations.

(d) Photos were provided with each reclamation report. Some provided herein may be duplicates.



Figure 1: Pre-exploration conditions. Note trees location for subsequent photo documentation.



Figure 2: Drill platform removed but pre-reclamation



Figure 3: Post reclamation



Figure 4: Helicopter landing pad. Note there was no vegetation disturbance at this site prior to exploration campaign.



Figure 5: Location of waterline near helicopter landing pad. No disturbance observed along the waterline route



Figure 6: Water pump contained in metal tub during mining campaign



Figure 7: Water pump site post reclamation

(e) Map with locations of all disturbed areas



Please feel free to contact me directly with any questions.

Respectfully submitted,

Angela M. Bellantoni

Angela M. Bellantoni Ph.D.

Cc: L. Komperdo, W. Felderhof and D. Felderhof