

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:	
Horvath Pit No 1	M-1977-546	Sand and gravel	La Plata	
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:	
Monitoring	Dustin Czapla	August 16, 2022	16:50	
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERA	TYPE OF OPERATION:	
Brice F Lee & Phyllis J Lee		110c - Construction	110c - Construction Limited Impact	
	T = 2 2 2			
REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:	BOND AMOUNT:	
Normal I&E Program	Complete Bond	\$1,376.00		
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGE	JOINT INSP. AGENCY:	
NA	None	None		
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:		
Clear	06	August 27, 2022		
	the			

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>N</u>	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING <u>N</u>	(SF) PROCESSING FACILITIES N	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE <u>N</u>	(RV) REVEGETATION <u>N</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION <u>N</u>	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS <u>N</u>	(OD) OFF-SITE DAMAGE <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: M-1977-546 INSPECTOR'S INITIALS: DMC INSPECTION DATE: August 16, 2022

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the operator was not present. Photographs are included with this report in order to illustrate conditions observed.

The Horvath Pit No 1 is located approximately 7.4 miles south of Hesperus and accessed from Hwy 140. The site is a 110c operation that includes a total of 3.0 permitted acres. The Division currently holds a financial warranty amount of \$1,376.00 for this site. The Division has reviewed the reclamation costs, in order to ensure the financial warranty reflects the actual current cost of fulfilling the requirements of the Reclamation Plan, and determined that the current financial warranty amount is sufficient.

Adequate mine identification signage was noted at the entrance to the site.

Reclamation at the site is complete. Final grading is adequate and vegetative cover is well established. One small stockpile of crushed gravel remains on site.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, 1313 Sherman Street Room 215, Denver, Colorado, 80203, phone number (303) 866-3567, ext. 8188.







Inspection Contact Address

Brice F Lee & Phyllis J Lee 940 CR 119 Hesperus, CO 81326