



STATE OF
COLORADO

Ebert - DNR, Jared <jared.ebert@state.co.us>

C-1996-084, Lorencito Canyon Mine, Pond Inspection Report Review

Ebert - DNR, Jared <jared.ebert@state.co.us>
To: Nick Mason <nmason@newelkcoal.com>
Cc: Brock Bowles <brock.bowles@state.co.us>

Fri, Sep 23, 2022 at 11:29 AM

Hello Nick,

Please see the attached review letter for the above referenced report. For future reports, one correction needs to be made, please see the letter for details.

Thanks,

Jared

--

Jared Ebert

Senior Environmental Protection Specialist

***I am working remotely, please feel free to call my cell at (720) 413-6466**



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567 ext. 8120 | F 303.832.8106 |

Physical: 1313 Sherman Street, Room 215, Denver, CO 80203

Mailing: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

jared.ebert@state.co.us | <https://drms.colorado.gov/>



2Q2022_PondInspReview_C1996084_23Sep2022_JLE1.pdf
246K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

September 23, 2022

New Elk Coal Company, LLC.
Attn: Mark Gray
12250 Highway 12
Weston, Colorado 81091

**Re: Lorencito Canyon Mine; C-1996-084
Second Quarter 2022 Pond Inspection Report Review**

Dear Mr. Gray:

The Colorado Division of Reclamation, Mining, and Safety (Division) has reviewed the above referenced report. This report appears to be in compliance with Rule 4.05.9 (14) and (17). The report included inspection report forms for each of the ponds inspected.

The inspection was conducted by Vince Massarotti on June 20, 2022 and the report was stamped by Bill Stormes a Colorado Licensed Professional Engineer. No appearances of structural weaknesses or hazardous conditions were noted. In accordance with Rule 4.05.9(17), please retain a copy of the reports at or near the mine site.

It was noted that on the certification page of the report, there is the following statement, "Inspections completed in compliance with Rule 4.09.1(11)(b) must be submitted to the Division within two weeks of completion." This rule pertains to reports filed regarding excess spoil and does not apply to these pond inspection reports required by Rule 4.05.9(17), please revise this in future reports

If you have any questions feel free to contact me at Jared.Ebert@state.co.us or (303) 866-3567 ext. 8120.

Sincerely,

Jared Ebert
Senior Environmental Protection Specialist

Ec: Nick Mason; NECC, nmason@newelkcoal.com

