

STATE OF
COLORADO

Cazier - DNR, Tim <tim.cazier@state.co.us>

RE: Pikeview monitoring report

1 message

Kos, Paul <paul.kos@stantec.com>

Wed, Nov 2, 2022 at 8:58 AM

To: "Cazier - DNR, Tim" <tim.cazier@state.co.us>

Cc: Jerald Schnabel <jerald_schnabel@castleaggregate.com>

Tim,

Please find responses to your questions below.

A) The paragraph at the bottom of p. 5 references Tables 3a and 3b. Only Table 3 is included (p. 7). Was Table 3 split into two parts "A" & "B" and left out of the final draft, or was the split table 3 part of an interim draft, then changed back to a single table?

The reference to Tables 3a and 3b was inadvertently left from the previous report. Table 3 is a single table in the August 2022 report, and there is not a Table 3a and 3b.

B) The shop disposal item summary in Appendix E lists 5 items as "Onsite": Pressure washer, Compressor, Bridge crane, Drill Oil 55 gallon Drum, and Hydraulic Oil 5 gallon Buckets. I have two questions related to these items:

i) Does this mean these items are buried on site, or that they are still on site waiting to be disposed of offsite?

They were not buried. They remain on site waiting to be sold (crane), be hauled off and recycled (oils), or are waiting to be picked up by the buyer (pressure washer and compressor).

ii) If they were/are to be disposed of onsite, please provide some detail as to how, where and what efforts were made to ensure no petroleum byproducts or other hazardous materials were disposed of onsite.

None of these materials were buried onsite, and they will not be buried onsite in the future. Any chemicals (i.e., new or used motor oil) are being stored onsite per SWPPP and SPCC, and they will be recycled or properly disposed offsite of by Safety-Kleen.

Item	Status	Planned Removal Method
Pressure washer	Pressure washer currently onsite pending pickup from the buyer.	Will be removed from the site. Waiting to be picked up by the buyer.
Compressor	Compressor currently onsite pending pickup from the buyer.	Will be removed from the site. Waiting to be picked up by the buyer.
Bridge crane	Onsite and attempting to sell.	Sell to buyer or haul to scrap metal recycling operation.

Drill Oil 55-gallon Drum	Oil consolidated into 250-gallon tote. Empty Drum was disposed of in scrap metal bin and will be sent to Colorado Industrial recycling. Drum was stored per SWPPP and SPCC.	Oil tote will be hauled off and properly disposed of/recycled by Safety-Kleen. Oil tote being stored per SWPPP and SPCC.
Hydraulic Oil 5-gallon Buckets	Oil buckets were emptied into 250-gallon tote. Empty buckets were sent to landfill. Buckets were stored per SWPPP and SPCC.	Oil tote will be hauled off and properly disposed of/recycled by Safety-Kleen. Oil tote being stored per SWPPP and SPCC.

Let me know if you have any other questions.

Thanks,
Paul

Paul Kos P.E., P.Eng.

Mine Development Services Manager

Mining, Minerals and Metals

Mobile: 303 570-9163
paul.kos@stantec.com

Stantec
2000 South Colorado Boulevard Suite 2-300
Denver CO 80222-7933



The content of this email is the confidential property of Stantec and should not be copied, modified, retransmitted, or used for any purpose except with Stantec's written authorization. If you are not the intended recipient, please delete all copies and notify us immediately.

Please consider the environment before printing this email.

From: Cazier - DNR, Tim <tim.cazier@state.co.us>
Sent: Wednesday, September 28, 2022 2:05 PM
To: Kos, Paul <paul.kos@stantec.com>
Cc: Jerald Schnabel <gerald_schnabel@castleaggregate.com>
Subject: Re: Pikeview monitoring report

Paul, Jerry:

I have some follow-up questions on the August report:

- A) The paragraph at the bottom of p. 5 references Tables 3a and 3b. Only Table 3 is included (p. 7). Was Table 3 split into two parts "A" & "B" and left out of the final draft, or was the split table 3 part of an interim draft, then changed back to a single table?
- B) The shop disposal item summary in Appendix E lists 5 items as "Onsite": Pressure washer, Compressor, Bridge crane, Drill Oil 55 gallon Drum, and Hydraulic Oil 5 gallon Buckets. I have two questions related to these items:
- i) Does this mean these items are buried on site, or that they are still on site waiting to be disposed of offsite?
 - ii) If they were/are to be disposed of onsite, please provide some detail as to how, where and what efforts were made to ensure no petroleum byproducts or other hazardous materials were disposed of onsite.

Thanks.

Tim Cazier, P.E.

Environmental Protection Specialist III - Engineering

Mobile: 303-328-5229



P 303.866.3567 x8169 | F 303.832.8106 | C 303.328.5229

Mailing Address: Division of Reclamation, Mining & Safety, Room 215, (optional: c/o: Tim Cazier), 1001 E 62nd Ave., [Denver, CO 80216](#)

Physical Address: [1313 Sherman St., Room 215, Denver, CO 80203](#)

tim.cazier@state.co.us | <https://drms.colorado.gov>

On Mon, Sep 26, 2022 at 4:22 PM Kos, Paul <paul.kos@stantec.com> wrote:

Tim,

Please find attached the Pikeview monitoring report for August. It includes a summary of the shop demolition. Let me know if you have any questions.

Paul Kos P.E., P.Eng.

Senior Geological Engineer

Mining, Minerals and Metals

Mobile: 303 570-9163
paul.kos@stantec.com

Stantec
[2000 South Colorado Boulevard Suite 2-300](#)
Denver CO 80222-7933



The content of this email is the confidential property of Stantec and should not be copied, modified, retransmitted, or used for any purpose except with Stantec's written authorization. If you are not the intended recipient, please delete all copies and notify us immediately.

Please consider the environment before printing this email.