



November 17, 2022

Bernard Buster
ELB Stone, Inc.
2493 CR 37 E
Lyons, CO 80540

Re: Buster Quarries, Permit M-1981-107, Receipt of Corrective Action Documentation

Dear Mr. Buster:

The Division received your response to a Compliance Problem cited in the Division's report from the inspection that was conducted on February 15, 2022. The status of the corrective action in regard to the cited problem is as follows:

Compliance Problem, Hydrologic Balance: The site is improperly impounding surface runoff or exposing groundwater without approval from the Division of Water Resources. This problem is considered to be resolved as a result of the following photographs from you, sent via email on November 17, 2022. The photographs show that the pit has been filled with rubble.





If you have any questions, please contact me at Rob.Zuber@state.co.us or by calling (720) 601-2276.

Thank you,



Robert D. Zuber, P.E.
Environmental Protection Specialist

Cc: Michael Cunningham, DRMS