

PERMIT INFORMATION

Permit Number: C-1996-083 Mine Name: Bowie No. 2 Mine Operator: Bowie Resources, LLC Operator Address: Mr. Basil Bear P.O. Box 1488 Paonia, CO 81428 County: Delta Operation Type: Underground Permit Status: Active Ownership: Private

Operator Representative Present:

Basil Bear

Operator Representative Signature: (Field Issuance Only)

INSPECTION INFORMATION

Inspection Start Date: November 29, 2022 Inspection Start Time: 07:45 Inspection End Date: November 29, 2022 Inspection End Time: 10:15			Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Cloudy	
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post	Inspection Contacts:	
None				
Inspector(s):	Inspecto	r's Sig	nature:	Signature Date:
Robert Zuber, P.E.	Phet	Chat D. 24		
				12/1/2022

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

- Y Air Resource Protection
 R Availability of Records
 Y Backfill & Grading
 NA Excess Spoil and Dev. Waste
 NA Explosives
 R Fish & Wildlife
 R Hydrologic Balance
- Y Gen. Compliance With Mine Plan
- N Other
- **R** Processing Waste

R - Roads

- Y Reclamation Success
- Y Revegetation
- Y Subsidence
- **R** Slides and Other Damage
- **R** Support Facilities On-site
- Y Signs and Markers
- ${\bf R}\,$ Support Facilities Not On-site
- Y Special Categories Of Mining
- **R** Topsoil

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on November 29, 2022. Parts of the site were not accessed due to icy roads, including Gob Pile #2 and the Utility Bench. However, these areas were viewed from afar.

Basil Bear was on site throughout the inspection (although not with the inspector in the field), and he was in the office during the records review and for a pre-inspection discussion.

BRL continues to focus their efforts on Gob Pile #3, and they have recently been spreading the coverfill material. Basil Bear showed the inspector drone photographs from November 21, 2022. In these photographs, progress spreading the material was evident, but Basil indicated that the work will not likely continue in 2022 due to weather. It appears that the backfilling, grading, topsoiling, and seeding will be completed in 2023.

The weather was cloudy and cold. The ground was mostly covered with snow.

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

The records were found to be very well organized. Please see the Availability of Records form in this report.

FISH and WILDLIFE – Rule 4.18:

Many deer were seen onsite.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Four sediment ponds were inspected: B, F, J, and K. None of the ponds were discharging. None of the ponds contained significant water; ice and snow were well below spillways. No significant problems were identified with embankments, spillways, inlet channels, or other features of the ponds.

Ponds C and D were not inspected, but the area directly below these ponds (near the old power plant) was inspected, and no signs of problems with Ponds C and D were identified.

Based on review of Basil Bear's drone photographs, the ditches and erosion control practices on Gob Pile #3 are functioning well.

PROCESSING WASTE/COAL MINE WASTE PILES – Rule 4.10 and 4.11 Drainage Control; Surface Stabilization; Placement:

Overall the gob piles appeared stable. No large puddles or other significant problems were observed.

ROADS – Rule 4.03 Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

The road to the portals, and the slopes adjacent to the roads, were in good condition.

SLIDES and DAMAGE - Rule 4.12:

It appears that slumps have not moved significantly in the recent past. These include slumps by the B Portal and by Curve Number 11 along the Haul Road.

SUPPORT FACILITIES - Rule 4.04:

The following areas appeared stable with no signs of erosion:

- Utility Bench
- D Portal bench
- B Portal bench
- The storage area east of the D Portal bench
- Material storage area beside Topsoil Stockpile A
- Conveyor corridors
- Slopes above and below the Coal Stockpile Pad
- The area around the office
- The Preparation Plant and nearby water tank
- Pump House and Filter Building
- Old power plant
- Storage area west of Pond D
- The Unit Train Loadout.

OFFSITE SUPPORT FACILIITES - Rule 4.04, 4.28:

The Hubbard Creek facilities (Vent Shaft pad and Rock Laydown area) were not accessed due to safety concerns (icy road).

TOPSOIL – Rule 4.06 Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4:

No erosion or other problems were seen with topsoil stockpiles or coverfill piles.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Northeast portion of Gob Pile #3



Northwest portion of Gob Pile #3



Road to Gob Piles 1, 2, and 4







Topsoil Stockpile A



Slump above B Portal



Area above Curve 10 near the B Portal



Slope below the D Portal



Pond J



Railroad tracks west of the Unit Train Loadout

AVAILABILITY OF RECORDS

PERMIT RECORDS DRMS Permit	Exp. 4 April 2022	HYDROLOGIC RECORDS NPDES Permit	CO-0044776,
	(RN-05 in review)		Exp.Sept. 2024
Permit Application w/Revisions	yes	NPDES Records (DMRs)	Through October 2022
Findings Document	RN4, 20 Novmbr. 2017	Stormwater Management Plan	Revised January 2020
Insurance Certificate	Expires 1 May 2023	SPCC Plan	May 2013
Bond Documents	SEE COMMENT 1	MSHA Pond Inspections	NA
Phased Bond Release	SL2,		NA
Documents/Findings	30 Decmbr. 2016	State Engineer's Pond Inspection	
Air Emission Permits	98DL0726 Exp. 2024	Quarterly Pond Inspections	3Q 2022
County Special Use Permits	NA	Annual Hydrology Reports	2021
UG Mining Landowner Notification	Several years	Ground Water Monitoring	yes
Subsidence Monitoring Reports	NA	• Surface Water Monitoring	yes
Subsidence Monitoring Data	NA	• Spring & Seep Monitoring	NA
Rill & Gully Survey	March 1, 2022	 Mine Water Discharge Monitoring 	NA
Vegetation Monitoring Data	NA	Mine Inflow Study	NA
Specific Variance Approvals	NA	• Water Consumption Records	NA
Annual Reclamation Reports	2021	Well Permits	NA
Midterm Review Documents	MT5, 3 October 2019		
DRMS/OSM Inspection	Through		
Reports/Enforcement Actions	October 2022	BLASTING RECORDS	
Transfers/Succession of Operator	10 August 2009	Blasting Publication	NA
Temporary Cessation Notification	NA	Blasting Records (3 years)	NA
Reclamation Cost Estimate	SEE COMMENT 2	ATFE Explosives Permit	NA
CERTIFICATIONS		Blasting Variances	NA
Pond Certifications	2Q 2022	Pre-Blast Surveys	NA
Fill Certifications for Underground Development Waste	Vol. IV for Gob Pile #1	ADDITIONAL RECORDS (specify)	
Quarterly Inspections	3Q 2022	SWMP Report	January 2022
Compaction Testing	October 2022	<u> </u>	
• Final Certification	NA		
Certs. for Coal Processing Waste Banks	Vols IX, XI (Gob Piles 2, 3, 4)		
Haul Road Certifications	1998 and 2013		
Access Road Certifications	Map 15 series		

COMMENTS:

1. Bond documents entail five corporate sureties (Lexon Company) for total of \$10,971,057.58:

C-1996-083/Bowie No. 2 Mine

- Bond # 1071397 for \$3,154,277.10
- Bond # 1071402 for \$1,024,357.97
- Bond # 1071403 for \$2,500,000.00
- Bond # 1071404 for \$2,217,169.51
- Bond # 1071405 for \$2,075,253.00.
- 2. The RCE for MT-05 totaled \$10,149,223. Additional \$311 from TR-119.