



Graham Roberts
Trapper Mining Inc.
P.O. Box 187
Craig, CO 81626

28 December 2022

Re: Trapper Mine (Permit No. C1981-010)
Review of November 2022 Discharge Monitoring Reports

Dear Mr. Roberts:

The Division has received and reviewed the November 2022 Discharge Monitoring Reports (DMRs), for the Trapper Mine. The DMR's were received by the Division on 12 December 2022 electronically. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged:

- Johnson System Pond #10, NPDS 10
- No Name Pond #5, NPDS 002
- Middle Flume System, NPDS 020

Trapper reported that none of the outfalls requiring WET testing discharged, 009A (Middle Pyeatt), 023A (East Flume).

The Division does not have any questions, concerns or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us

