



**COLORADO**

**Division of Reclamation,  
Mining and Safety**

Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

February 7, 2023

Basil Bear  
Bowie Resources, LLC  
P.O. Box 1488  
Paonia, CO 81428

**Re: Bowie No. 1 Mine (Permit No. C-1981-038),  
RN-08 Preliminary Adequacy Review (PAR)**

Dear Mr. Bear:

The Division has completed its preliminary review for a permit renewal (RN-08) for the Bowie No. 1 Mine in accordance with Rule 2.08.5. The review included the application form and other materials submitted by Bowie Resources, LLC (BRL) on August 25, 2022, the Permit Application Package (PAP) for this mine, the 2021 Annual Reclamation Report, and other documents such as hydrology reports. The Division has identified the following items that require an additional submittal or clarification. As applicable, please consider updates to all parts of the PAP, including Volume 7 for the loadout.

### **Application Form**

1. Please confirm the acreages in the application form, and explain any discrepancies with recent Annual Reclamation Reports (ARRs) or other documents related to this permit. This check should include, but not be limited to, the number of acres that have been bond released. The application contains acreages that are different than the acreages in the 2021 ARR. For example, the RN-08 application value for 100 percent release is 10.38 acres, but in the 2021 ARR this value is 13.38 acres; the value should not have decreased. If revisions to the form are necessary, please mail a hard copy with an original signature to the Division office on Sherman Street (in addition to an electronic submittal of your entire response to this PAR).

### **PAP Text, Appendices and Maps**

2. Section 2.03.4 – If there have been any changes to the ownership and control information for BRL since MT-08, this section should be updated.



3. Section 2.03.5 – The page should be updated, as necessary, to reflect current conditions. In the footer, the date and revision number should be updated.
4. Section 2.03.6 - In the adequacy response, please indicate if all right of entry and lease agreements are current. If they are not current, please update the PAP accordingly.
5. Section 2.04.11 - In the adequacy response, please indicate if the Threatened and Endangered Species discussion in this section is based on current lists issued by the U.S. Fish and Wildlife Service and the Colorado Division of Parks and Wildlife (per Rule 2.04.11(4)). If it is not based on current lists, please check the current lists and update the PAP accordingly.
6. Section 2.05.4
  - a. In the recent text in this section (pages 58 to 60d), there is no discussion regarding the remaining reclamation for borehole pads and associated roads. Please add this discussion to these pages or, in this text, reference other pages in Section 2.05.4 where this information can be found.
  - b. Pages 60 through 60c describe past reclamation activities for the East Mine. However, it appears that road improvement activities are not included in this description. Please add this text. The Division also requests that the adequacy response (the letter, not the revised PAP) correlate these actions to tasks in the reclamation cost estimate (e.g., Tasks 41, 49, 52, 54, 59, 64, and 65).
  - c. There appears to be an additional page 60i in the Division's copy of Section 2.05.4 (after the letter from the BLM). The footer states that this was created with TR-28 in 1998. Please advise if this page should be deleted or if the page number should be changed.
  - d. On page 62 in Section 2.05.4, text states that, "There is no topsoil." Will topsoil be hauled in from offsite? If so, please revise the text accordingly.
  - e. Confirm that the status of boreholes is current. This includes the table on pages 2.05-79i and 2.05-79ii. Regarding locations of the SG series of holes, please provide information in this table such as a reference to a map. For example, are they shown on Map No. 8A-8? Is the "Stevens Gulch Well Field" the same thing as the "Cyprus Orchard Valley Well Field"? In this table, DH23 is listed as "open" and sealed. What does that mean?
  - f. Regarding the tunnel under Black Bridge Road, what will be used to fill that? Describe in the text what the type and source of material will be.
  - g. Provide an approximate schedule for future reclamation activities at the loadout, including the year of the reclamation.
  - h. Add a discussion on the plan for the asphalt roads at the loadout.
7. Map 8A-19 – The areas depicted with colors on the map should be revised to reflect SL-08.

An update of the Reclamation Cost Estimate (RCE) for the Bowie No. 1 Mine will be completed after the above adequacy items are addressed.

If you have any questions or comments, please do not hesitate to contact me at [Rob.Zuber@state.co.us](mailto:Rob.Zuber@state.co.us) or 720.601.2276.

Sincerely,

A handwritten signature in blue ink that reads "Robert D. Zuber". The signature is written in a cursive, flowing style.

Robert D. Zuber, P.E.  
Environmental Protection Specialist