



WEST FARM - DRMS M-2022-048 - Request for Extension of Corrective Action completion (from Pre-Op Insp Rpt dated 12/22/22)

Lynn Mayer Shults <lmshults@lgeverist.com>

Thu, Feb 23, 2023 at 10:22 AM

To: "Eric Scott - Division of Reclamation, Mining and Safety (eric.scott@state.co.us)" <eric.scott@state.co.us>

Cc: "environment-inc@outdrs.net" <environment-inc@outdrs.net>

Hello Eric,

We are requesting a short extension – from 2/28 to 3/10 – to complete one remaining Corrective Action noted in your inspection report (dated 12/22/22), from the Pre-Op inspection of West Farm (inspected 12/21/22). The report noted that “The permit boundaries, were not sufficiently marked for the pre-operation inspection.” And the corrective action to correct this problem would be (in part) as follows, “The boundaries of the affected area (permit in this case) must be marked by monuments or other permanent markers that are clearly visible and adequate to delineate such boundaries. The permit boundary will need to be appropriately surveyed and marked according to the location and setbacks given in the provided application documents. ...The permit boundary should be fully surveyed and marked no later than 2/28/23.”

As discussed just now in our phone conversation, L.G. Everist had scheduled a survey company to mark the permit boundaries as required. They were to do it this week, but with the snow and freezing temps, they are being delayed. They should be able to get it done next week, so the short extension of deadline (to 3/10/23) for this Corrective Action should be sufficient.

Thank you, for your understanding, and once the permit boundaries are marked, L.G. Everist will send you proof of the completion of corrective action.

If you have any questions, please let me know,

LYNN

LYNN MAYER SHULTS, Regulatory Manager – cell-303-514-2778

L.G. EVERIST, INC. ~ SAFE - RELIABLE - PRODUCTIVE

7321 E 88th Avenue, Suite 200, Henderson, CO 80640

office-303-286-2247 ~ lmshults@lgeverist.com