



Graham Roberts
Trapper Mining Inc.
P.O. Box 187
Craig, CO 81626

3 March 2023

**Re: Trapper Mine (Permit No. C1981-010)
Review of January 2023 Discharge Monitoring Reports**

Dear Mr. Roberts:

The Division has received and reviewed the January 2023 Discharge Monitoring Reports (DMRs), for the Trapper Mine. The DMR's were received by the Division on 27 February 2023 electronically. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in January:

- Johnson System Pond #10, NPDS 10
- No Name Pond #5, NPDS 002
- Middle Flume Pond; NPDS 020

Trapper reported that none of the outfalls requiring WET testing discharged; acute 009A, (Middle Pyeatt), 023A (East Flume).

The Division does not have any questions, concerns or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us

