

## Supplemental Information

M1992074

While completing the survey for the 2023 Annual Report, it was discovered that the perimeter road extended past the permit boundary by approximately 10 feet. Upon this discovery, the perimeter road was realigned to fall within the permit boundary. No mining activity occurred within this area. The amount of disturbed area was approximately 300 square feet. This area is planned to be seeded once weather conditions allow. This area is shown on the annual report map.