

Forest Service Roads
Inspection Form

Date: 2-28-23

Time: 12:00P

Name of Inspector: N. Poulos

Current Panel and XC Being Mined: 553

Road(s) Being Inspected: N/A

Yes No

☐ ☒ Is the Forest Service road within the projected angle of draw of subsidence? If yes, which road(s):

☐ ☐ Are there visible surface cracks on the road? If yes, describe (location, width, length, etc.):

☐ ☐ Is there any recent evidence of potential subsidence induced slope failure? If yes, describe:

☐ ☐ Are there any other potentially damaging, subsidence induced features on or near the road? If yes, describe:

☐ ☐ Is mitigation needed? If yes, list suggestions:

Notes:

no access - winter conditions

Signature of Inspector: Nicolas Poulos

* If any potential subsidence induced features are observed that could cause harm to the public or operations, notify Jessica Wilczek immediately.