Stock Pond Inspection Form

Date: 3-13-23 Time: Name of Inspector: N. Poulos Current Panel and XC Being Mined: 553 Stock Pond(s) Being Inspected:		
Yes	No	
	PI	Is the stock pond within twice the projected angle of draw of subsidence? If yes, which pond(s):
		Are there visible surface cracks in or near the stock pond? If yes, describe (location, width, length, etc.):
		Is there any evidence of potential subsidence induced water loss? If yes, describe:
		Is there water in the pond? If yes, describe:
		Is mitigation needed? If yes, list suggestions:
Notes:		
	yvo	access - winter conditions
Signature of Inspector. MCOUPriloo		

* If any potential subsidence induced features are observed that could cause harm to the pond, notify Jessica Wilczek immediately.

(W \MCC-Engineering\ENV PERMITTING\REG AGENCIES\CDRMS\Inspection-Survey_USFS Ponds & Rds\Ponds\Stock Pond Inspection Form)