



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

June 2, 2023

Julie Mikulas
Martin Marietta Materials, Inc.
1800 N. Taft Hill Road
Fort Collins, CO 80521

**RE: Home Office Mine, M-1977-439
Technical Revision submission
Decision Date Extension**

Dear Ms. Mikulas:

June 1, 2023, the Division of Reclamation, Mining and Safety received your request for an extension date for a Technical Revision. MMM committed to submitting a TR by May 31, 2023 with a design for a groundwater drain on the north side of the G1 reservoir. This commitment is documented in the February 7, 2023, AM4 application, Adequacy Response 3, question 40f. The decision date has been extended from May 31, 2023 to June 14, 2023.

Since we last spoke, the county assignments for Larimer County has changed. Patrick Lennberg is the specialist in charge of the Home Office Pit. Patrick can be contacted at patrick.lennberg@state.co.us.

If you have any questions, please contact me at (720) 774-0040 or brock.bowles@state.co.us.

Sincerely,

Brock Bowles
Environmental Protection Specialist



May 31, 2023

Mr. Brock Bowles
Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

RE: M-1977-439 Amendment 4, Adequacy Review Item 40.f.

Dear Mr. Bowles:

In our last adequacy review response prior to approval of Amendment 04, for Comment 40.f., we agreed to design an underdrain for the north side of G-I and submit it to the DRMS by May 31, 2023 as a Technical Revision. We agreed that the drain would be installed if groundwater levels in the monitoring wells are within 4 feet of the ground surface for more than 2 consecutive months.

Please accept this letter as our request for a two-week extension until June 14, 2023 to submit the Technical Revision. We got the first round of the design back from the engineers today and just need a little time to review and make final edits.

Also, wanted to let you know that Loveland Ready Mix to the north of G-I is questioning whether irrigation water on the surface of the cornfields is being caused by the liner. We recently received a significant rain and we are filling G-I with free river water which could be causing the issue as the ditch overflowed for a short period of time. We are working on getting the irrigation return flow ditch cleaned out so water flows freely and we will also be monitoring the situation to see if it improves. Recent well monitoring logs will be submitted shortly for this quarter after we pull the June data.

Please contact me at 970-407-3631 if any additional information is needed at this time.

Sincerely,



Julie Mikulas
Regional Land Manager