



Graham Roberts
Trapper Mining Inc.
P.O. Box 187
Craig, CO 81626

6 June 2023

Re: Trapper Mine (Permit No. C1981-010)
Review of April 2023 Discharge Monitoring Reports

Dear Mr. Roberts:

The Division has received and reviewed the April 2023 Discharge Monitoring Reports (DMRs), for the Trapper Mine. The DMR's were received by the Division on 1 June 2023 electronically. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in April:

- Johnson System Pond #10, NPDS 10
- No Name Pond #5, NPDS 002
- East Pyeatt Pond #2, NPDES 011
- Middle Flume Pond, NPDS 020
- East Middle Flume Pond, NPDES 21

Trapper reported that none of the outfalls requiring WET testing discharged; acute 009A, (Middle Pyeatt), 023A (East Flume).

The Division does not have any questions, concerns or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us

