

Cortner DRMS Annual Report 2023

Question 2 – in the recent inspection it was noted that some of the fences do not sit on the permit boundary. We are working on getting the property surveyed to establish the true boundaries.

Question 14 – in the recent inspection it was noted that there are a few tamarisk, we are working on removing

Question 19 – new calculations by DRMS show that we need to increase the bond amount, a rider has been requested with our insurance company