

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review 2023 May DMR's Trapper Mine

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Thu, Jul 13, 2023 at 10:24 AM

To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Graham,

Attached please find the Division's Review of the May 2023 Trapper Mine DMR's. Thank you for the timely submission of the reports. The Division has no concerns.

Kind Regards

Robin Reilley, M.S. GISP **Environmental Protection Specialist II**



P 303.866.3567 ext 8105 | F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us

Review_DMR_2023_05May_Trapper.pdf 269K



Graham Roberts Trapper Mining Inc. P.O. Box 187 Craig, CO 81626

13 July 2023

Re: Trapper Mine (Permit No. C1981-010)
Review of May 2023 Discharge Monitoring Reports

Dear Mr. Roberts:

The Division has received and reviewed the May 2023 Discharge Monitoring Reports (DMRs), for the Trapper Mine. The DMR's were received by the Division on 22 June 2023 electronically. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in May:

- o Johnson System Pond #10, NPDS 10
- o East Pyeatt Pond #2, NPDES 011
- o Middle Flume Pond, NPDS 020
- o East Middle Flume Pond, NPDES 21
- o Deal Pond, NPDES 22

Trapper reported that none of the outfalls requiring WET testing discharged; acute 009A, (Middle Pyeatt), 023A (East Flume).

The Division does not have any questions, concerns or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP

Environmental Protection Specialist II

Robin.reilley@state.co.us

