

PERMIT INFORMATION

Permit Number: C-1996-084 Mine Name: Lorencito Canyon Mine Operator: New Elk Coal Company, LLC Operator Address: Mr. Nick Mason	County: Las Animas Operation Type: Surface Permit Status: Permanent Cessation Ownership: Private			
12250 Highway 12	Operator Representative Present:			
Weston, CO 81091	Nick Mason			
Operator Representative Signature: (Field Issuance Only)				

INSPECTION INFORMATION

Inspection Start Date: August 23 Inspection Start Time: 14:00 Inspection End Date: August 24, Inspection End Time: 14:00			Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspecto	r's Sig	gnature: Signature Date	: :
Brock Bowles	Brok	Da	ls	
Amber Michels	/	•	September 1, 2023	

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection N - Roads

R - Availability of Records **N** - Reclamation Success

N - Backfill & Grading N - Revegetation

N - Excess Spoil and Dev. Waste N - Subsidence

N - Explosives
 N - Slides and Other Damage
 N - Fish & Wildlife
 N - Support Facilities On-site
 R - Hydrologic Balance
 N - Signs and Markers

N - Gen. Compliance With Mine Plan N - Support Facilities Not On-site

N - Other N - Special Categories Of Mining

R - Processing Waste N - Topsoil

COMMENTS

This complete inspection was conducted by Brock Bowles and Amber Michels of the Division of Reclamation, Mining and Safety (Division). Nick Mason of the New Elk Mine was present for the inspection. The weather was clear with few scattered clouds, warm, with a light breeze. The ground was mostly dry.

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

The mine records were checked in the mine office. The records check list is available at the end of this report.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Pond 6 contained a small amount of water and was not discharging (photo 1).

Pond 8 contained water and was not discharging (photo 2).

Pond 9 contained water and was not discharging. The primary and emergency spillways were clear of obstructions.

Pond 9A contained water and was not discharging.

Culvert C4 was clear of obstructions (photo 3).

PROCESSING WASTE/COAL MINE WASTE PILES – Rule 4.10 and 4.11

Drainage Control; Surface Stabilization; Placement:

Fill 6 has many gullies which have undercut the wattles. The fill has not stabilized and needs to be reconstructed and revegetated (photo 4).

Fill 7 was well vegetation and appeared stable.

Fill 8 was well vegetated and appeared stable.

Fill 9 was well vegetated and appeared to be stable.

DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Photo 1 – Pond 6



Photo 2 – Pond 8



Photo 3 – Culvert C4 discharge end



Photo 4 – Fill 6 rills and gullies

AVAILABILITY OF RECORDS

PERMIT RECORDS		HYDROLOGIC RECORDS	
DRMS Permit	X-RN5 in	NPDES Permit	X, on extension
	progress, exp.		since 2020
Parmit Application w/Payirians	2022 X	NPDES Records	n/o
Permit Application w/Revisions Findings Document	X (RN4 2018)		n/a
Insurance Certificate	X-2024	Stormwater Management Plan SPCC Plan	n/a
Bond Document	X X	MSHA Pond Inspections	n/a
Phased Bond Release	X SL-1 (2005),	Wishia i olid hispections	n/a
Documents/Findings	SL-2(2018)	State Engineer's Pond Inspection	11/ a
Air Emission Permits	X	Quarterly Pond Inspections	n/a
County Special Use Permits	Exempt	Annual Hydrology Reports	CDPHE cover
County Special CSC 1 crimis	Exempt	Timidal Hydrology Reports	letter
UG Mining Landowner Notification	n/a	 Ground Water Monitoring 	n/a
Subsidence Monitoring Reports	n/a	 Surface Water Monitoring 	n/a
Subsidence Monitoring Data	n/a	• Spring & Seep Monitoring	n/a
Rill & Gully Survey	X, submitted 2023	 Mine Water Discharge Monitoring 	n/a
Vegetation Monitoring Data	n/a	Mine Inflow Study	n/a
Specific Variance Approvals	n/a	Water Consumption Records	n/a
Annual Reclamation Reports	X, submitted 2023	Well Permits	X, #201451
Midterm Review Documents	MT-4		
DRMS/OSM Inspection			
Reports/Enforcement Actions (3			
Years)	X through July		
	2023	BLASTING RECORDS	
Transfers/Succession of Operator	X, Jan. 2021	Blasting Publication	n/a
Temporary Cessation Notification	n/a	Blasting Records (3 years)	n/a
Reclamation Cost Estimate	MT-4 2016 and RN-4 2017	ATFE Explosives Permit	n/a
CERTIFICATIONS		Blasting Variances	n/a
Pond Certifications	5,6A,7A,8,9,9A,10	Pre-Blast Surveys	n/a
Annual Certifications for Impoundments	1 st Quarter		
Fill Certifications for Excess Spoil	X, 2023 through	ADDITIONAL RECORDS	
or Underground Development Waste	June	(specify)	
 Quarterly Inspections 	1st Quarter		
 Compaction Testing 	n/a		
 Final Certification 	n/a		
Coal Processing Waste Banks	n/a		
Haul Road Certifications	n/a		
Access Road Certifications	n/a		
COMMENTS:			



Bowles - DNR, Brock

 brock.bowles@state.co.us>

August Inspection reports

1 message

Bowles - DNR, Brock

brock.bowles@state.co.us>

Fri, Sep 1, 2023 at 4:12 PM

To: Nick Mason <nmason@newelkcoal.com>

Cc: Amber Michels - DNR <amber.michels@state.co.us>

Nick,

Here are the Aug inspection reports for the New Elk (M-1981-012) and Lorencito (M-1996-084) mines. Have a good weekend,

Brock

Brock Bowles

Environmental Protection Specialist



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

P 720.774.0040 | O 303.866.3567

Physical: 1313 Sherman St., Room 215, Denver, CO 80203 Mailing: Room 215, 1001 E 62nd Ave, Denver, CO 80216 brock.bowles@state.co.us | https://drms.colorado.gov

2 attachments



INSP-REPORTC_C1996084_ANM_09012023010722.pdf



INSP-REPORTC_C1981012_ANM_09012023120701.pdf 3274K