

Reilley - DNR, Robin <robin.reilley@state.co.us>

## **Review DMRs Trapper Mine 2023 July**

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Fri, Aug 25, 2023 at 10:10 AM

To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Mr. Roberts,

Please find the Divisions' Review of the July 2023 DMRs for Trapper Mine. No concerns were noted.

Thank you

Robin Reilley, M.S. GISP **Environmental Protection Specialist II** 



P 303.866.3567 ext 8105 |

F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us

Review\_DMR\_2023\_07\_July\_Trapper.pdf 268K



Graham Roberts Trapper Mining Inc. P.O. Box 187 Craig, CO 81626

9 August 2023

Re: Trapper Mine (Permit No. C1981-010)

**Review of June 2023 Discharge Monitoring Reports** 

Dear Mr. Roberts:

The Division has received and reviewed the July 2023 Discharge Monitoring Reports (DMRs), including the acute monthly Wet testing results for the Trapper Mine. The DMR's were received electronically by the Division on 24 August 2023. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in July:

- o Johnson System Pond #10, NPDS 10
- o No Name Pond #5 NPDES 002
- East Pyeatt Pond #2, NPDES 011

Trapper reported that none of the outfalls requiring acute WET testing discharged. Monthly DMRs for discharging outfalls: 001, 002, and 011, indicated that no parameters were exceeded.

The Division does not have any questions, concerns or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP

Environmental Protection Specialist II

Robin.reilley@state.co.us

