

Reilley - DNR, Robin <robin.reilley@state.co.us>

## Review: Sediment Pond reports 2023 Q2 Yoast, Seneca IIW

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Mon, Sep 25, 2023 at 1:20 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Afternoon Miranda,

Thank you for the timely submission of the 2023 Q2 Sediment Pond Reports for Yoast and Seneca IIW mine sites. Please find DRMS's reviews of Sediment Pond reports.

The Division has no concerns at this time.

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



P 303.866.3567 ext 8105 |

F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us

## 2 attachments



SedPondReview\_Yoast\_2023\_Q2.pdf



25 September 2023

Miranda Kawcak Moffat County Mining, LLC 29515 Routt County Road #27 Oak Creek, CO 80467

RE: Seneca IIW Mine Permit; C1982057 DRMS Review Sediment Pond Inspections 2023 Quarter 2

Dear Ms. Kawcak:

Thank you for your submittal of the 2023 quarter two sediment pond inspection report for the Seneca IIW site. The Colorado Division of Reclamation, Mining and Safety (The Division), has reviewed the above referenced reports, received by The Division on 14 August 2023. Sediment pond inspections were conducted by Jason Herden on 26 June 2023.

This reports appear to be in compliance with the applicable sections of Rule 4.05.9. In June Pond 6 was discharging at the time of inspection at the rate of 86.0 gallons per minute (gpm), Pond 15 at 13.6 gpm, Pond 16 at 71.6 gpm and Pond 17 at 14.7 gpm. Not all Stock Tanks held water at the time of inspection.

The Division has no concerns at this time.

Best Regards,

Robin Reilley, M.S. GISP

**Environmental Protection Specialist II** 

