



STATE OF  
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

---

## Review Development Drilling Trapper\_2023

1 message

---

**Reilley - DNR, Robin** <robin.reilley@state.co.us>

Thu, Oct 19, 2023 at 3:58 PM

To: Tonia Perkins <tonia.perkins@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Ms. Perkins,

Please find the review of the 2023 Development Drilling Report for Trapper Mine.

Thank you for the timely submittal of the report.

Sincerely

Robin Reilley, M.S. GISP  
Environmental Protection Specialist II



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) ext 8105 |

F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

[robin.reilley@state.co.us](mailto:robin.reilley@state.co.us) | <http://mining.state.co.us>



**Review\_DevDrillingReport2023.pdf**

226K



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

19 October 2023

Tonia Perkins  
Trapper Mine, Inc.  
P.O. Box 187  
Craig, Colorado 81626

**RE: Trapper Mining Inc., Permit; C1981010**  
**Review: Development Drilling Abandonment Report 2023**

Dear Ms. Perkins:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS), has reviewed and found the above referenced report to be in general compliance with *Rule 4.07.3 Permanent Sealing*, with respect to CDRMS regulations.

The report details the 7 exploration holes drilled in the year 2023. The Division received the report via electronic transmission on 18 October 2023. The report comprises the location information, depth and diameter of drill holes, how the holes were drilled and sealed, and the date abandoned as per the afore mentioned rule (4.07.3). A map indicating the location of each hole was also included.

Based on the information submitted, it appears the drill holes were abandoned using methods approved in section 3.3 of the Trapper Mining, Inc, permit and rule 4.07.3.

DRMS has no questions at this time. Thank you for the timely submission of the Trapper Mine 2023 Drill Hole Abandonment Report.

I am available to answer any questions that come up.

Best Regards

Robin Reilley, M.S. GISP  
Environmental Protection Specialist II  
(303) 899-2762 ext 8105  
[Robin.reilley@state.co.us](mailto:Robin.reilley@state.co.us)

