

Reilley - DNR, Robin <robin.reilley@state.co.us>

## **Review DMR's October 2023 Trapper Mine**

1 message

 Reilley - DNR, Robin <robin.reilley@state.co.us>
 Wed, Nov 22, 2023 at 1:40 PM

 To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Afternoon Mr. Roberts,

Please find the Divisions' Review of the October 2023 DMRs for Trapper Mine. DRMS noted no concerns.

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



P 303.866.3567 ext 8105 | F 303.832.8106 Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us

Review\_DMR\_2023\_10October\_Trapper.pdf 265K



Graham Roberts Trapper Mining Inc. P.O. Box 187 Craig, CO 81626

22 November 2023

## Re: Trapper Mine (Permit No. C1981-010) Review of October 2023

Dear Mr. Roberts:

The Division has received and reviewed the October 2023 a Discharge Monitoring Reports (DMRs), including the chronic and acute WET testing results for the Trapper Mine. The DMR's were received electronically by the Division on 20 November 2023. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in October

- Johnson System Pond #10, NPDS 001
- No Name Pond #5 NPDES 002

Trapper reported that none of the outfalls requiring acute monthly WET testing discharged. Monthly DMRs for discharging outfalls: 001 and 002, indicated that no parameters were exceeded.

The Division does not have any questions, concerns or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Bobin Keiller

Robin Reilley, M.S. GISP Environmental Protection Specialist II <u>Robin.reilley@state.co.us</u>

