


Gold Basin Placer located in Section 5

T12S, R80W, 6th P.M., Chaffee County, Colorado



Bearings were based on the intersection line of the Lost Canyon Placer and the Gold Basin Placer, per the BLM Resurvey of Section 5, as shown hereon.
Reference Bearing: South

Contour interval = 2 feet

Elevations were assumed and based on 1000 feet
1000 in relative elevation = approximately 12,000 in
real elevation

- Denotes set $\frac{5}{8}$ " x 24" rebar with a 1" plastic cap stamped "PLS 37060"
- Denotes found 4"x4" wood post

Acreage Summary

Total Permit Area = 32.3 acres
Pre-1950 Disturbed Area = 3.8 acres
Active Mine Area = 11.0 acres
External Mine Roads outside of Active Mine Area
(50 foot buffer) = 3.7 acres



SURVEY DESCRIPTION:
A portion of the Gold Basin Placer (M.S. 54496)

SURVEYOR'S CERTIFICATION:
I hereby state that this survey and plat was prepared by me or under my direct responsibility, supervision and checking, and that, in my professional opinion, it is true and correct to the best of my knowledge, belief and information based on the standards of care of Professional Land Surveyors practicing in the State of Colorado.

John E. Mower, P.L.S.
Colorado Registration No. 37060

Figure 1
CDRMS 2023
Annual Report

Mountain Man Surveying

2855 North Main, Suite B106
Durango, Co. 81301
Phone: 970-375-6358
Fax: 970-259-3147
Cell: 970-946-1886

Gold Basin Placer
located in Section 5
T12S, R80W, 6th P.M., Chaffee County, Colorado

Prepared By: J.E.M.	
Checked By: J.E.M.	Project No: 14373
Date: 10-31-14	Page 1 of 1