

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review DMR's Trapper 2023 Nov

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us> Tue, Dec 26, 2023 at 9:41 AM To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Mr. Roberts,

Please find the Divisions' Review of the November 2023 DMRs for Trapper Mine. No concerns were noted.

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



P 303.866.3567 ext 8105 | F 303.832.8106 Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us

Review_DMR_2023_11Nov_Trapper.pdf 263K



Graham Roberts Trapper Mining Inc. P.O. Box 187 Craig, CO 81626

26 December 2023

Re: Trapper Mine (Permit No. C1981-010) Review of November DMR's 2023

Dear Mr. Roberts:

The Division has received and reviewed the November 2023 Discharge Monitoring Reports (DMRs), including the chronic and acute WET testing results for the Trapper Mine. The DMR's were received electronically by the Division on 18 December 2023. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in November.

- o Johnson System Pond #10, NPDS 001
- No Name Pond #5 NPDES 002
- East Pyeatt #2 NPDES 011
- Middle Flume NPDES 020

Trapper reported that none of the outfalls requiring WET testing discharged. Monthly DMRs for discharging outfall indicated that no parameters were exceeded.

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP Environmental Protection Specialist II Robin.reilley@state.co.us

