



STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

ADQ3 M2018030 TR1

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Tue, Jan 16, 2024 at 4:42 PM

To: David Kotz <DaveK@sgm-inc.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Hi Dave,

I have a couple of questions as attached.

Thank you

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) ext 8105 |

F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>



ADQ3_TR1_M2018030.pdf

228K



Mr. Dave Kotz
SGM
118 w. Sixth St. Suite 200
Glenwood Springs, CO 81601

12 January 2024

RE: Adequacy #3 M2018030 TR1

DRMS has noted changes to the Town of Granby Mine Plan with the response to the Adequacy #2 questions. These changes to the mine plan constitute a deviation from the technical revision submitted. The following changes are outlined below:

DRMS notes that in the Town of Granby affected area as per Exhibit C-c, the soil type is classified as 93 with the nomenclature of Youga loam with slopes of 1 to 6% as per soils Map j(B). A portion of the area appears as Bald Eagle winter forage on permit Map H. No specific vegetation type is delineated for the Town of Granby affected area as per Map J(2).

Noted change: Topsoil spreading depth changed from to 4 to 6 inches to **3 to 6 inches**.

Appendix F

In Section F of the submission, description of the reclamation plan the following item was omitted:
v) topsoiling

1. Please update this with the new topsoil depth.
2. The submitted document with Adequacy #2 on page 9 jumps to (b), is out of sequence and has no heading. DRMS is unsure what section of the permit page 9 corresponds to and therefore unable to correctly insert the information into the appropriate place in the permit. More specificity is required as to where this belongs in the permit with respect to other permit sections.

The Exhibit C, mine plan map calls out two areas in the River Run Permit Area as currently being mined under permit M2021001.

3. Please describe: To what extent the Town of Granby is conducting mining in this area?

Sincerely,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us

