

Michael Hart to Chad, me, Bill, Jeff, Whitey -

Rob,

If it's ok with you I prefer to reply to your request for a letter via this email.

Page 2 of your Inspection report dated December 19, 2023 states as follows:

Inspection Topic: Signs & Markers Problem/Possible Violation: Problem:

"The affected area boundary markers are missing at the southeast corner of the permit area."

Response:

My recent email to you dated Monday, January 16, 2024 included the following:

A map prepared by King Surveyors titled **"Poudre Ponds Minor Subdivision"** which is a metes and bounds description of Tract "A" also known as the Permit Area. The included map identified all the property boundary pins for Tract "A" placed by King Surveyors. The boundary shown in the southeast corner of subject property identifies courses L1, L2 and L3 as shown on page 2 of King Surveyors Exhibit A (**Property Description**). The legend associated with the Poudre Ponds Minor Subdivision map shows that the two property line end points of L3, in the southeast corner of the permit area, are identified as "Calculated Positions" due to the fact that at the time the survey was done these points were determined to be in the Pouder River.

Furthermore, because the south boundary of the permit area, as surveyed by King, includes portions of the Poudre River, the King surveyors installed a set of "offset pins" in the field that are parallel to and 100 feet south of the true property boundary adjacent to and in some cases in the Poudre River. Therefore, based on the Tract A map documentation prepared by King Surveyors as previously submitted to the Division, all boundary markers are in place save those calculated positions that were determined to be in the Poudre River at the time of the Survey.

Rob, Please let me know if the Division would prefer to have a 24"x 36" paper copy of the "Poudre Ponds Minor Subdivision" map as an aid to determining that there are no missing boundary markers related to Tract A. Alternatively, if you prefer, Cottonwood can request a written statement from King Surveyors confirming the above. Let me know.

Hope this helps, Mike

EXHIBIT A (1 of 2) PROPERTY DESCRIPTION

Tract A, Poudre Ponds Minor Subdivision, recorded May 29, 2012 as Reception No. 3848721 of the records of the Weld County Clerk and Recorder, located in the Northwest Quarter (NW1/4) of Section Thirty-six (36), Township Six North (T.6N.), Range Sixty-six West (R.66W.) of the Sixth Principal Meridian (6th P.M.), City of Greeley, County of Weld, State of Colorado.

Said described parcel of land contains 38.159 acres, more or less (±), and may be subject to any rights-of-way or other easements of record or as now existing on said described parcel of land.

Said described parcel of land contains 0.090 acre, more or less (\pm) , within 25' radiuses of 2 plugged and abandoned well heads.

SURVEYORS STATEMENT

I, Michael Chad Dilka, a Colorado Licensed Professional Land Surveyor do hereby state that this Property Description was prepared under my personal supervision and checking and that it is true and correct to the best of my knowledge and belief.





Michael Chad Dilka - on behalf of King Surveyors Colorado Licensed Professional Land Surveyor #38106

KING SURVEYORS

650 East Garden Drive Windsor, Colorado 80550 (970) 686-5011

JN: 20210286





LEGEND

	EASEMENT
	SECTION LINE
National States and the second states	QUARTER SECTION LINE
	RIGHT-OF-WAY
	PROPERTY LINE
	FEMA FLOODPLAIN
	FOUND ALIQUOT CORNER AS DESCRIBED
	FOUND #4 REBAR WITH A YELLOW PLASTIC CAP STAMPED LS 22098
۲	FOUND #4 REBAR WITH A ORANGE PLASTIC CAP STAMPED KSI, LS 33642
Δ	FOUND MAG NAIL WITH A BRASS TAG STAMPED KSI, LS 33642
0	SET #4 REBAR WITH A GREEN PLASTIC CAP STAMPED KSI, LS 34995
0	CALCULATED POSITION

