

6473 County Road 120
Hesperus, CO 81326

970.385.4528 ext. 6540
mdickson@gcc.com



January 24, 2024

State of Colorado
Division of Reclamation, Mining & Safety
1313 Sherman St., Room 215
Denver, CO 80203

Attn: Environmental Protection Specialist

Re: GCC Energy, LLC, King II Mine
CDRMS Permit # C-1981-035
Re: 4th Quarter 2023 Surface Subsidence Inspections
4th Quarter 2023 Huntington Ditch Inspections

Mr. Wein:

Mike and Marc Crawford, of the Crawford Ranch property informed us that they continue to monitor subsidence cracks on their property. No new cracks have been located this quarter. They have informed us that all cracks on the Crawford Ranch property are minor, and they will inform us if they feel action is required.

No subsidence issues have been noticed in the mined-out areas west of Pine Gulch on the Huntington ranch property. Dan Huntington has not mentioned any subsidence related issues on other areas of his property.

Please contact me at 970.385.4528 ext. 6540, or mdickson@gcc.com if you have any questions or require any additional information.

Sincerely,

Michael Dickson

Michael Dickson
Mine Engineer
GCC Energy, LLC