

Reilley - DNR, Robin <robin.reilley@state.co.us>

## Review\_2023\_Q4DMRS\_WF

1 message

**Reilley - DNR, Robin** <robin.reilley@state.co.us> Fri, Feb 16, 2024 at 10:21 AM To: "Kawcak, Miranda" </Kawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Miranda,

Please find DRMS's review of the above mentioned compliance report for the Williams Fork mine. No concerns were noted.

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



**COLORADO** Division of Reclamation, Mining and Safety Department of Natural Resources

P 303.866.3567 ext 8105 | F 303.832.8106 Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us

Review\_DMR\_WF\_Dec2023.pdf 213K



16 February 2024

Miranda Kawcak Environmental Manger Peabody, Colorado Operations

## Re: Williams Fork (Permit No. C1981044) Review DMRs 2023 Q4

Dear Ms. Kawcak:

Thank you for your timely submittal of the 2023 quarter four DMR reports that include chronic WET testing results for the Williams Fork Mine. The report covers the time period from 1 October through 31 December 2023. The Colorado Division of Reclamation, Mining and Safety (The Division) received the above referenced reports on 1 February 2024. Moffat County Mining LLC submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Moffat County Mining reported that none of the outfalls requiring WET testing discharged. Quarterly DMRs for outfalls indicated that none of the outfalls discharged during the quarter.

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Bobin Keill

Robin Reilley, M.S. GISP Environmental Protection Specialist II <u>Robin.reilley@state.co.us</u>

