

STATE OF
COLORADO

Ridley - DNR, Hunter <hunter.ridley@state.co.us>

Canon Dolomite Quarry Sediment Control

Wyatt WEBSTER <wyatt.webster@holcim.com>

Thu, Mar 7, 2024 at 2:40 PM

To: Hunter Ridley - DNR <hunter.ridley@state.co.us>, Kurt THURMANN <kurt.thurmann@holcim.com>

Cc: Lu Toxvard <lu.toxvard@holcim.com>

Hunter,

Please reference inspection report and the corrective action calling for additional sediment containment measures. The sediment containment berms were added. Please let me know if you have any questions.

Thank you,

Wyatt Webster
Environmental & Land Manager
Holcim - WCR, Inc.
1687 Cole Blvd., Suite 300
Golden, CO, 80401
United States
Phone (702) 379-4623
wyatt.webster@holcim.com
www.holcim.us

BUILDING PROGRESS FOR
PEOPLE AND THE PLANET.

This email is confidential and intended only for the use of the above named addressee. If you have received this email in error, please delete it immediately and notify us by email or telephone.

3 attachments



Fremont Quarry Repair 001.JPG
10288K



INSP-REPORTMWP_M1977376_TC1_2023-09-14_Binder2 (2).pdf
3435K



Sediment Trap Berm.kmz
1K

